

**BERRIEN COUNTY DRAIN COMMISSION
CHIKAMING TOWNSHIP
JAN TO SEPTEMBER 2022 UPDATES**

Work order #	Drain Name	Initial contact date	Notes	% Complete	Districts	Township	Address
WO #22-020	Tiffany/Orchard Beach #521	Thu 1/20/22	Old cistern/catch basin on property near Red Arrow. Is this part of the system?	38%	9	Chikaming	Lakeside Ave, Lakeside
WO #22-025	Minnich Rd #062	Tue 1/25/22	Dip & grub 1000' +/- from Minnich Rd to Sawyer Rd.	87%	9	Chikaming	5088 Sawyer Rd, Sawyer
WO #22-055	Sawyer Village Drain #448	Mon 2/28/22	Flooding over road & in field @ last rain/thaw event	100%	9	Chikaming	12965 Peck Ave, Sawyer
WO #22-057	Wolcott #562	Tue 3/1/22	Flooding at road, even when freezing. Says Public Works says it isn't broken pipes. This home is not very close to drain, but he says it goes down the road and heads to their home. Please evaluate our drain....	86%	9	Chikaming	12270 Linden Ave, Sawyer
WO #22-057.1	Wolcott #562	Tue 3/1/22	Flooding at road, even when freezing. Says Public Works says it isn't broken pipes. This home is not very close to drain, but he says it goes down the road and heads to their home. Please evaluate our drain.....	100%	9	Chikaming	12270 Linden Ave, Sawyer
WO #22-058	Union Pier #535	Wed 3/2/22	2' of debris & leaf litter in drain, trees have fallen in too. Says they are bad from Locke Rd north to his property....	26%	9	Chikaming	9517 Union Pier Rd, Union Pier

WO #22-069	Sawyer Village Drain #448	Fri 3/11/22	Check inlets multiple locations for debris & clear, check grate at outlet of pond for debris and clear.	100%	9	Chikaming	Trash rack & culverts, see photo
WO #22-092	Wolcott #562	Thu 3/17/22	Locate existing tile and repair. Near 12270 Linden Ave.	32%	9	Chikaming	12270 Linden, Sawyer
WO #22-100	Wolcott Avenue #680	Fri 3/25/22	Flooding, drain backed up...	89%	9	Chikaming	12395 Wolcott Avenue, Sawyer
WO #22-100.1	Wolcott Avenue #680	Fri 4/29/22	Flooding, drain backed up...	100%	9	Chikaming	12395 Wolcott Avenue, Sawyer
WO #22-100.2	Wolcott Avenue #680	Tue 6/28/22	Camera obstruction found at cleaning from Miguel Rd south.	32%	9	Chikaming	12395 Wolcott Avenue, Sawyer
WO #22-118	Sawyer Village Drain #448	Mon 4/4/22	Check inlets multiple locations for debris & clear, check grate at outlet of pond for debris and clear.	100%	9	Chikaming	Trash rack & culverts, see photo
WO #22-134	Olsen #381	Tue 4/5/22	As Olsen flows under I-94, water is backing up into the field. There is standing water now.	100%	9	Chikaming	Take exit 11
WO #22-153	Sawyer Village Drain #448	Tue 4/19/22	Check culvert/tube	99%	9	Chikaming	North of Arlington Drive, on Sawyer Rd, Sawyer
WO #22-169	Sawyer Village Drain #448	Fri 4/29/22	Check inlets multiple locations for debris & clear, check grate at outlet of pond for debris and clear.	100%	9	Chikaming	Trash rack & culverts, see photo
WO #22-190	Sawyer Village Drain #442	Wed 5/4/22	Minor flooding at creek, downed trees approx. 50' north of Pine Lane culvert.	32%	9	Chikaming	6623 Pine Lane, Sawyer
WO #22-233	Sawyer Village Drain #448	Tue 5/31/22	Check inlets multiple locations for debris & clear, check grate at outlet of pond for debris and clear.	100%	9	Chikaming	Trash rack & culverts, see photo

WO #22-249	Union Pier # 535	Mon 6/6/22	Trees down, and leaves collecting in branches causing damming. There is a large pile of leaves right at the end of drain before it goes into tile. He has raked what he can reach to create a flow. The trees are about 800-900' from Union Pier Rd....	100%	9	Chikaming	9517 Union Pier Rd, Union Pier
WO #22-261	Lakeside #287	Fri 6/17/22	Ditch at RR easement overgrown & sluggish. Home owner's son concerned about flooding, as house is surrounded by drain. Please remove vegetation.	0%	9	Chikaming	8770 East St, Three Oaks
WO #22-262	Streed #503	Fri 6/24/22	Sink hole along road edge	32%	9	Chikaming	16024 Red Arrow Hwy, off Goodwin, Union Pier
WO #22-273	Sawyer Village Drain #448	Thu 6/30/22	Check inlets multiple locations for debris & clear, check grate at outlet of pond for debris and clear.	100%	9	Chikaming	Trash rack & culverts, see photo
WO #22-308	Sawyer Village Drain #448	Wed 7/27/22	Check inlets multiple locations for debris & clear, check grate at outlet of pond for debris and clear.	100%	9	Chikaming	Trash rack & culverts, see photo